


**PLAN DE SITUATIE** scara 1:500



**PLAN INCADRARE IN ZONA** scara 1:2000

Verificator/Expert	Nume	Semnatura	Cerinta	Referat / Expertiza Nr. / Data
<b>S.C.HACHIKO DESIGN S.R.L</b> J 40 / 2127 / 2010 str. DINU VINTILA nr. 11, et.8, cam 8, sector 2				<b>BENEFICIAR:</b> Primaria Sectorului 8 <b>Proiect nr.:</b> 25/2011
Specificatie	NUME	Semnatura	Scara: 1:2000 1:500	<b>Titlu proiect:</b> Expertiza tehnica, Audit energetic, DALI-HOTAC-PT-CS-DE Verificare si Adaptare tehnica pt. Locuitorii de reabilitare termica 273 blocuri, Sector 8, Bucuresti <b>Bloc "OD8", Alina Polana Vedulul, nr.1</b>
Self proiect	arh. Luminita POPOESCU			<b>Faza:</b> DALI
Proiectat	arh. Romina DEBRECZENI		<b>Data:</b> 2011	<b>Titlu plan:</b> PLAN DE SITUATIE PLAN DE INCADRARE IN ZONA
Desenat	arh. Romina DEBRECZENI			<b>Plan nr.:</b> A 01